



# advanced FLOW engineering

## TECHNICAL BULLETIN

No: 06-50029

PRODUCT P/N affected by this bulletin

46-20049 Intercooler Tube Upgrade  
46-20059 Intercooler Tube Upgrade

DATE ISSUED:

May 26th, 2010

MAKE:

GM

MODEL:

Duramax -  
LLY/LBZ & LMM

YEARS:

2004-2007  
2007.5-2009

ENGINE:

V8 - 6.6L (td)



GM LLY/LBZ '04-'07



P/N 46-20049



GM LMM '07.5-'09



P/N 46-20059

### **Concern:**

Interference may occur between the brake line and the aFe intercooler tube upgrade. This could potentially cause damage to the brake line. For these situations, aFe has developed a bracket relocate plate to ensure sufficient clearance.

### **Step 1:**

Please check the gap between of the brake line and the aFepower intercooler tube upgrade (See Fig. 1). Does the brake line touch the intercooler tube?

### **Step 2:**

If it touches or is very close, please contact aFePower by phone at (951)493-7100 or email [tech@afepower.com](mailto:tech@afepower.com) to request bracket relocater plate (P/N 05-60049). Upon receipt of proof of purchase, aFePower will send you the bracket relocater plate free of charge.

### **Step 3:**

Install the plate as shown in Fig 2, moving the brake line closer to the frame and away from the aFepower intercooler tube upgrade.

If you have any questions, please call aFe at (951)493-7100.

Figure 1



Figure 2

